


Raychem 2SC-STC

END TERMINATION KIT INSTALLATION INSTRUCTIONS



APPROVALS

Hazardous Locations



Class I, Div. 2, Groups A, B, C, D Class II, Div. 2, Groups F, G Class III



[1] for T-Rating, see design documentation

DESCRIPTION

The 2SC-STC is a NEMA 4 rated end termination kit designed for use with Raychem 2SC30, 40, 50 (-CT), 2SC/H30, 40, 50 (-CT) and 2SC/F30, 40, 50 (-CR) series heating cables in hazardous locations.

This kit may be installed at temperatures as low as -40°F (-40°C). For easier installation, store above freezing until just before installation.

For technical support, call Pentair Thermal Management at (800) 545-6258.

TOOLS REQUIRED


- · Utility knife
- Diagonal cutters
- Wire strippers
- Disposable towel or rag
- Soldering tool or torch (with small tip)
- Thomas & Betts WT2000 crimp tool or equivalent (P/N 273435-000) Crimp tools can be ordered from Pentair Thermal Management.

ADDITIONAL MATERIALS REQUIRED

- · Glass cloth tape:
 - GT-66 for installation temperature above 40°F (4°C)
 - GS-54 for installation temperature above -40°F (-40°C)

KIT CONTENTS

Item	Qty	Description			
A	1	Metal end cap			
В	1	Rubber collar			
С	3	Tape strips (2 required, 1 extra)			
D	1	ETL-END-SEAL label			
Е	1	Coil of Kester® 48 core LF solder for nickel			
F	2	Parallel splices (large), spare included			
G	2	Parallel splices (small), spare included			
Н	1	KE 1204 silicone rubber potting compound Part A			
I	1	KE 1204 silicone rubber potting compound Part B			
J	2	Stir sticks			
K	2	Material Safety Data Sheets (not shown)			



WARNING:

This component is an electrical device that must be installed correctly to ensure proper operation and to prevent shock or fire. Read these important warnings and carefully follow all of the installation instructions.

- To minimize the danger of fire from sustained electrical arcing if the heating cable is damaged or improperly installed, and to comply with the requirements of Pentair Thermal Management, agency certifications, and national electrical codes, ground-fault equipment protection must be used. Arcing may not be stopped by conventional circuit breakers.
- Component approvals and performance are based on the use of Pentair Thermal Management-specified parts only. Do not use substitute parts or vinyl electrical tape.
- Damaged conductors can overheat or short. Do not break conductor wire strands when scoring the jacket or removing insulation.
- Keep components and heating cable ends dry before and during installation.
- Use only fire-resistant insulation materials, such as fiberglass wrap or flame-retardant foam.
- Soldering tools or torches can cause fire or explosion in hazardous areas. Be sure there are no flammable materials or vapors in the area before using these tools.
- Wrap exposed conductors with supplied tape strips to prevent shorts.


CAUTION:


HEALTH HAZARD: Hot solder can burn eyes and skin. Fumes during soldering are irritating to eyes and may cause headache and respiratory system irritation or damage. Prolonged or repeated exposure to rosin flux fumes during soldering may result in allergic reaction in a sensitive person, resulting in asthma symptoms. Consult MSDS VEN0043 for further information.


Silicone rubber compound Part B, may generate flammable and explosive hydrogen gas if it comes in contact with an acidic, basic or oxidizing material. Personal contact with the silicone rubber compound may cause slight eye or skin irritation. Consult MSDS VEN0030 and VEN0031 for further information.


CHEMTREC 24-hour emergency telephone: (800) 424-9300


Non-emergency health and safety information: (800) 545-6258.












- Lightly score around and down to remove 3/8-inch (10 mm) inner jacket.
- Remove 5/16-inch (8 mm) insulation and fiberglass braid to expose the bare conductors.
- Position collar 1 3/8-inch (35 mm) from end of heating cable.

5

- Twist the conductors together.
- Use the WT2000 crimp tool and appropriate splice to crimp heating cable conductors together (see table).
- Crimp splice twice.

			inomas & Bett	(S (I & D)	
	Heating cable ⁽¹⁾	Heating cable conductor size	Splice Catalog no.	Splice size	Crimp tool die
Ī	2SC30-CT	18 AWG	B14-PS-M	Small	Non-Insul
Ī	2SC40-CT	16 AWG	B14-PS-M	Small	Non-Insul
Ī	2SC50-CT	14 AWG	C10-PS-D	Large	Non-Insul

 $^{[1]}$ The above table is also applicable for 2SC/H30, 40, 50 (-CT) and 2SC/F30, 40, 50 (-CR) heating cables. For replacement spices, call Pentair Thermal Management at (800) 545-6258.






⚠ WARNING: Fire and Health Hazard

Soldering tools or minitorches can cause fire or explosion in hazardous areas. Be sure there are no flammable materials or vapors in the area before using these tools. Follow all site safety guidelines when working in hazardous areas.


- Use only solder provided with kit. Only Kester 48 core LF has been qualified with SC cables.
- Refer to solder material safety data sheet packaged with kit.
- Heat the splice using a soldering tool, or propane or MAPP gas torch. Note: MAPP gas may be required if the connections are being soldered at temperatures below -4°F (-20°C). Heat the center of the splice until it is hot enough to melt the solder placed at the end. Allow the splice to cool before proceeding to the next step.



7

IMPORTANT: To ensure proper electrical insulation, use the specified high temperature Teflon® tape provided with the kit. Do not use common vinyl tape that does not have adequate temperature rating.

• Wrap the crimped connection with two strips of tape, covering splice and 1/4 inch (6 mm) of conductor insulation (approximately three overlapped layers). DO NOT WRAP THE BRAID WITH TAPE



8

⚠ WARNING: Health Hazard Refer to silicone rubber material safety data sheet packaged with kit.











- Open the two containers: one labeled Part A, and the other Part B.
- Use separate wooden sticks to stir the contents of each container until smooth and homogeneous.
- Pour all the contents of the container labeled Part B into the container labeled Part A and mix thoroughly until the color is uniform.





5/6



WWW.THERMAL.PENTAIR.COM

NORTH AMERICA

Tel: +1.800.545.6258 Fax: +1.800.527.5703 Tel: +1.650.216.1526 Fax: +1.650.474.7711 thermal.info@pentair.com EUROPE, MIDDLE EAST, AFRICA

Tel: +32.16.213.511 Fax: +32.16.213.603 thermal.info@pentair.com ASIA PACIFIC

Tel: +86.21.2412.1688 Fax: +86.21.5426.2917 cn.thermal.info@pentair.com LATIN AMERICA

Tel: +55.11.2588.1400 Fax: +55.11.2588.1410 thermal.info@pentair.com

Pentair and SC are owned by Pentair or its global affiliates. All other trademarks are the property of their respective owners. Pentair reserves the right to change specifications without prior notice.

© 2005-2013 Pentair. PN 864596-000

THERMAL MANAGEMENT SOLUTIONS | EN-Raychem2SCSTC-IM-H57826